Instruction Steps

MODEL: WT2 PRO

1. Align the rear pad with the velcro

2. Align the snap on one side with the VR insert

3. Remove VR goggle assembly

4. Pass the bag through the card slot at the front of VR

5. Reinstall the goggle assembly

6. Plug in the charging port, and start VR after installation and adjustment

Instructions

❶	Charging Process	White light flashing
❷	Full Charge	White light is always on
❸	Discharge Process	White long bright
❹	Low Power	White lights flicker

Capacity: 6000mAh 20.14Wh
Add time: 3H
Output: 5V/2A
Input: 5V/2A
Weight: 440g
Color: White & Black

FC CE RoHS